



PCB1
80-0253

DOD			
8760 S. Sandy Parkway Sandy, Utah 84070			
Title DFX9 DELAY (POT BOARD) 80-0253			
Size B	Document Number 050253B2.001		Rev B2
Date:	Thursday, September 07, 2000	Sheet	1 of 1

&l0 (s0P (s15H (s8V (s0S &l6D &l66P &l3E &a7L &a120M &l61FDOD Software

Page 1

DFX9 DELAY (POT BOARD) 80-0253 Revised: February 28, 1994

050253B2.001 Revision: B2

Bill Of Materials February 28, 1994 15:51:19

Quan	Reference	Part	SYMAN	Description
------	-----------	------	-------	-------------

1	C13	.010	56-2022	0.010 uF Capacitor 10% 100V Polyester Film
2	C36,C37	10U	60-0049	10.0 uF Capacitor -20%,+80% 16V Electrolytic-S
2	H1,H2	HDR5+	32-1065	5 Pin Header, Right Angle 0.1" Cut from 7 Pin RA Hdr
1	P1	P20K 5C RK	40-2018	20 K "B" Rot Pot, Rack Leads, 5D
2	P3,P4	P100K W RK	40-2012	100 K "W" Rot Pot, Rack Style Leads
1	P5	P5K A RK	40-2017	5 K "A" Rot Pot, Rack Style Leads
1	PCB1	80-0253		
1	R8	2K	50-0013	2 KOhm Resistor 5% 1/4 Watt Carbon Film
1	R23	270	50-0065	270 Ohm Resistor 5% 1/4 Watt Carbon Film
1	R27	33K	50-0028	33 KOhm Resistor 5% 1/4 Watt Carbon Film